

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
7	BRS	L29	38230	(silicide or polycide or TiSi ₂)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 19:55			0
8	BRS	L35	11307	29 same (anneal\$4 or heat\$4 or bak\$4 or RTA or RTP)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 20:10			0
11	BRS	L53	288	35 and (C49 or C54)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 20:13			0
12	BRS	L59	194	53 and (W or Ge or Co or germanium or tungsten or cobalt)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 20:15			0
13	BRS	L65	33	59 and (stress or strain or compressive-stress or compressive-strain)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 20:16			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
6	BRS	L27	17322	(compress\$5 near3 (stress or strain)) or compressive-stress or compressive-strain	USPAT	2001/01/09 19:54			0
7	BRS	L29	38230	(silicide or polycide or TiSi\$)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 19:55			0
8	BRS	L35	11307	29 same (anneal\$4 or heat\$4 or bak\$4 or RTA or RTP)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 20:10			0
9	BRS	L41	113	35 and 27	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 19:58			0
10	BRS	L47	4	41 and (C49 or C54)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 19:59			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	24746	(compress\$5 near3 stress) or compressive-stress	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 17:50			0
2	BRS	L7	350	1 and (silicide or polycide or TiSi\$)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/01/09 18:38			0